

Band Pass Filter ZA-006P/ZA-007P/ZA-008P/ZA-009P/ZA-010P/ ZA-011P/ZA-012P/ZA-013P/ZA-014P/ZA-015P

General

The ZA-006P, ZA-007P, ZA-008P, ZA-009P, ZA-010P, ZA-011P, ZA-012P, ZA-013P, ZA-014P and ZA-015P Band Pass Filters eliminate environmental interference.

Safety Information

A caution alerts the user to possible injury or problems with the instrument associated with its use or misuse such as instrument malfunction, instrument failure, damage to the instrument, or damage to other property.

Pay attention to all safety information in the Operator's Manual or Installation Guide.

To avoid the possibility of injury to yourself or damage to the telemetry system or multiple patient receiver, remove the power cord from the telemetry system or multiple patient receiver before installing or removing any component from the telemetry system or multiple patient receiver.

Check that there is no smoke or smell from the telemetry system. If there is smoke or smell, remove the power cord from the telemetry system and contact your Nihon Kohden representative.

▲ CAUTION

Check that there is no smoke or smell from the multiple patient receiver. If there is smoke or smell, remove the power cord from the multiple patient receiver and contact your Nihon Kohden representative.

> This Safety and Performance Information is an extract from the general and safety information sections of the most recent edition of Operator's Manual or Installation Guide. Therefore, the contents of your Operator's Manual or Installation Guide may differ from those of this Safety and Performance Information. For detailed operating procedures, follow the instructions of your Operator's Manual or Installation Guide.

Manufacturer

NIHON KOHDEN CORPORATION 1-31-4 Nishiochiai, Shinjuku-ku, Tokyo 161-8560, Japan Phone +81 3-5996-8041 https://www.nihonkohden.com/

EC REP European Representative

NIHON KOHDEN EUROPE GmbH Raiffeisenstrasse 10, D-61191 Rosbach, Germany Phone +49 6003-827-0 Fax +49 6003-827-599